



Date: 3/3/2023

Region: 4C
FAC ID: WV014

CSS No.: 91853
Maximo Work Order No.: 12306

Asset #: NA

Original Work Request:

Rebuild and retest failed backflow.

Description of Repairs Needed:

Labor and material to a.) repair and retest the failed backflow using RK34-975XLR WILKN 3/4-1" 975XL RT - AMERICAN BACKFILOW, RK34-975XLC 3/4-1" 975XL - AMERICAN BACKFLOW and test for proper operation.

Material List:

(1) RK34-975XLR WILKN 3/4-1" 975XL RT - AMERICAN BACKFLOW
(1) RK34-975XLC 3/4-1" 975XL - AMERICAN BACKFLOW

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
10	\$1,385.99	\$790.77	\$2,176.76