



Date: 3/9/2023

Region: 4C
FAC ID: WV007

CSS No.: 92285
Maximo Work Order No.: 12334

Asset #: 6567

Original Work Request:

During the PM for the boiler Casto tech found that a sensor on the chiller was bad and needs replaced.

Description of Repairs Needed:

Labor and material to a.) replace the loop temperature sensor and suction line sensor on the Trane Chiller (M# CGAM080; S# U15B47125). b.) replace the flame sensor on the Triad Boiler (M# GPS-1600-SH; S# 57439).

Material List:

- (1) SEN02133 Temperature Sensor
- (1) SEN02039 Temperature Sensor
- (1) X04225-J 9-1/2 IN Flame Rod 90L62C-1
- (1) Flame Rod Cable 3' Parts Kit

Equipment List:

NA

PM WO History:

11076

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
12	\$1,663.20	\$332.64	\$1,995.84