



Date: 5/24/2023

Region: 4C
FAC ID: PA209

CSS No.: 92740
Maximo Work Order No.: 12514

Asset #: NA

Original Work Request:

Repair the hot water tank in the mechanical room of the OMS building. The blower motor is not working causing the hot water tank to not function correctly.

Description of Repairs Needed:

Labor and material to a.) Repair Hot Water Tank in Mechanical Rm, OMS Bldg by replacing the Blower Assembly

Material List:

(1) Blower Assembly - Model - AO Smith Products:
100111050 F/BTH Series

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
3	\$396.00	\$1,344.05	\$1,740.05

