



Date: 5/12/2023

Region: 4A  
FAC ID: PA035

CSS No.: 93052  
Maximo Work Order No.: 12576

Asset #: NA

#### Original Work Request:

Light on outside of drill hall POV area - closest one to motor pool is strobing. In addition we have a light on the back side of the training center (in the fenced in area) that the sensor is not working properly.

#### Description of Repairs Needed:

Labor and material to a.) replace Light Outside Drill Hall

#### Material List:

- (1) C-Lite LED Flood light w ½-inch adjustable fitter
- (1) Photocell (JL-423CZ)
- (1) LED Area Light, Type 3, 4000K/19,000 lumens (E-APR19A-T340B)
- (1) Adjustable fitter (E-SF-ADJ-FTR)

#### Equipment List:

NA

#### PM WO History:

NA

#### Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
4	\$494.01	\$492.22	\$986.23