



Date: 5/26/2023

Region: 4C
FAC ID: PA062

CSS No.: 93578
Maximo Work Order No.: 13005

Asset #: NA

Original Work Request:

Repair the hot water tank in the mechanical room of the OMS building. The blower motor is not working causing the hot water tank to not function correctly.

Description of Repairs Needed:

Labor and material to a.) replace the domestic valve on the hot water tank.

Material List:

3" Domestic Gate Valve (F-617-0)

Equipment List:

NA

PM WO History:

NA

Estimate Summary:

Labor Hours	Labor	Material/Equipment	Total Repair
11	\$1,512.00	\$1,742.40	\$3,254.40