

MD021, Rockville, MD

End of hallway where elevator is located. Lower level to MP Company starts.



## MD021

Transition area where the main training building and lower building was attached.

Location Photo: Blue Arrow shows area of leaks above doors. Transition areas where the building join together.



## Entrance Hall way

Location: Hall way as you come into the Training Building across from Restroom.

Leaks: above doorway where the Training building and Assembly hall transition. Both ends of this hallway leaks above the door ways.



## Assembly Hall

Flashing around Ductwork leaking.



## MD021 Rockville, MD

Location: Transition level same as above area. Soldiers placed large trash cans under door way to collect the rain water.

