

SERVICE REPORT

KONECRANES®
Lifting Businesses™

Report Created: Sep 16, 2021 1:47 PM

Customer and Service Information

Customer	CMI Management Inc		
Business Location	US Army Reserve - New Windsor, New Windsor, 910 Raz Ave		
City	New Windsor		
Agreement			
Service Request	1-94118729317		
Description	BOS (NHV) - Provide labor and material to replace pendant on asset 7.5 ton crane per Quote 1-178CKZKQ		
PO Number	WO NO. 14871		
Billing Type	Fixed		
Customer Contact	Joe Bayne 703-738-5304 joe.bayne@cmimgmt.com	Konecranes Contact	Ross Sanderson 4127879480 ross.sanderson@konecranes.com

Component Condition

✓ Acceptable (No issues detected)

! Need Attention

Assets

 **7.5 Ton Bridge Crane**
Single girder EOT - 1 trolley wire rope hoist

Manufacturer	KONECRANES	Span	20ft
Serial number	1190936	Lift	19.7ft
Criticality	High	Volt/Ph/Hz	480-3-60
Site Location	Maintenance Bay #6		
Capacity/SWL	7.5 Ton		
Model	A31500		
Service Products	Planned Repairs		

Electrics

Control system

✓ Pushbutton pendant		Repaired
Date Reported	Sep 16, 2021	
Technician	Cory Leonard	
Task Type	Change	
Fault Code	Damaged enclosure	
Risk	Safety Risk	
Recommendation	Repair	
Comment:	Turned off power removed back cover made a wire diagram. Removed wires from old pendant and wired in new pendant. Attached and adjusted strain relief. Tested all limits and functions all working at this time.	

SERVICE REPORT

KONECRANES®
Lifting Businesses™



Sep 16, 2021 10:59 AM Joe Bayne, Customer



Sep 16, 2021 11:02 AM Cory Leonard, Technician

Findings and Actions

Safety Risk **WARNING**

Indicates an unsafe condition. Failure to remedy such condition before continued operation of the identified Asset may result in personal injury including death, or property damage.

Production Risk

Indicates an inefficient condition. Failure to remedy such condition before continued operation of the identified asset may result in inefficient asset performance or an interruption in production.

Undetermined Condition

Indicates that the condition could not be directly verified through visual inspection as a result of asset configuration and/or obstruction.

The condition of certain components cannot be directly verified through visual inspection without further disassembly and/or the use of other inspection methods. These advanced services are generally excluded from the scope of typical compliance and preventive maintenance inspections. Consultation Services may be added to a Service Program or offered on a stand-alone basis to assess the condition of these components. Inspection frequency for these components should follow OEM recommendations and/or governing regulations. If no records are available, we recommend appropriate inspections be carried out to determine current condition and to establish a baseline for recurring inspections.

Improvement Opportunity

Indicates a potential opportunity to improve the safety, productivity, application or useful life of the asset.

Acceptable / Repaired Item

Component condition is verified by Konecranes service technician. No actions required. If a component or other object has been repaired within the service visit, green color code is shown as well.

KONECRANES® STORE

SPARE PARTS, ACCESSORIES AND SELECT
PRE-CONFIGURED LIFTING EQUIPMENT

store.konecranes.com

ONLINE
ANY TIME

YOURKONECRANES

CRANE MAINTENANCE INFORMATION
AND REMOTE MONITORING DATA

your.konecranes.com