

CASTO TECHNICAL SERVICES, INC.

SERVICE REPORT

DATE 9-13-23 ARRIVAL TIME DEPARTURE TIME JOB/TCK. NO. 200595

CUSTOMER P.O. NO. VA-WO13382 CSS93892

JOB NAME/LOCATION *USARC - South Ridge*

SERVICE REQUESTED (WV007) There is wet ceiling tile on 1st floor of facility outside room 136 indicating a possible leak. After

Manufacture: _____
Model#: _____
Serial#: _____
Refrigerant Added: Qty lb oz TYPE
Refrigerant Removed: Qty lb oz TYPE

- Leak Tested**
- Leak Found**
- Leak Repaired**

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO

Arrived on site, checked in with customer. Customer showed me where the leak was. Removed insulation from the cold water line. The 90 is leaking and will need to be replaced. Will quote the repair. Picked up and checked out.

NATURE OF WORK

Regular Service _____

Quoted Service _____

Start-up/Warranty _____

SPD _____

Contract Service _____

Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

SUMMARY OF TIME

JOB COMPLETE

YES NO EXPLAIN _____

SIGNATURE _____

Customer Representative