

CASTO TECHNICAL SERVICES, INC.

SERVICE REPORT

DATE 2025 1 8 ARRIVAL TIME DEPARTURE TIME JOB/TCK. NO. 214097

CUSTOMER P.O. NO. *FEMS 2934942*

JOB NAME/LOCATION USARC - Cross Lanes WV006

SERVICE REQUESTED (4) Investment is to replace the Hot Surface Igniters on Boilers #1 and #2. COW AND PICTURES

Manufacturer: Laars
Model#: CB-M2-250N
Serial#: H 09 212641

Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

Leak Tested

Leak Found

Leak Repaired

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO

Arrived on site, checked in with customer. Replaced igniters on boiler 1 and 2 boiler 2 ran ok boiler 1 has motor on order.

NATURE OF WORK

Regular Service _____

Quoted Service _____

Start-up/Warranty _____

SPD _____

Contract Service _____

Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

SUMMARY OF TIME

JOB COMPLETE YES NO EXPLAIN _____

SIGNATURE _____

Customer Representative