

## SERVICE REPORT

DATE 8-29-23

ARRIVAL TIME

DEPARTURE TIME

JOB/TCK. NO.

1.99889

CSS 94849. WO 13848

**JOB NAME/LOCATION** *USARC - Cross Lanes WV006*

**SERVICE REQUESTED** *(8) Investment is rebuilding the duct work around Trane RTU-3 (M# YSC120H3; S# 223415087L) to all proper*

Manufacture: _____				
Model#: _____				
Serial#: _____				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested

☐ Leak Found

☐ Leak Repaired

Method: \_\_\_\_\_

Total Charge: \_\_\_\_\_

**WORK PERFORMED/UNIT INFO.**

*Picked up materials from the supply house. Arrived on site, checked in with customer. Carried up tools needed to start the job. Started by removing part of the dog house that was going over the top. Started measuring out the angle needed to give as much of an opening as possible to the condenser coil. There was a wood frame underneath the enclosure due to the size of it. I had to go to lowes to pick up additional materials for the job. Returned to the job and carried up the materials. Cut out the needed length board to support the frame that is going to stay. Removed the pieces that were no longer needed and moved the other securing piece to match the angle I was wanting to achieve. Secured all of the boards and made sure they were in the correct*

### NATURE OF WORK

Regular Service \_\_\_\_\_  
Quoted Service \_\_\_\_\_  
Start-up/Warranty \_\_\_\_\_  
SPD \_\_\_\_\_  
Contract Service \_\_\_\_\_  
Energy Management \_\_\_\_\_

### PARTS, MATERIALS AND SUBCONTRACTED SERVICES

[illegible]

### SUMMARY OF TIME

[illegible]

JOB COMPLETE YES X NO        EXPLAIN       

**SIGNATURE** \_\_\_\_\_

**Customer Representative**

## CASTO TECHNICAL SERVICES, INC.

## SERVICE REPORT

DATE \_\_\_\_\_ ARRIVAL TIME 9:11 pm DEPARTURE TIME \_\_\_\_\_ JOB/TCK. NO. 199889CUSTOMER P.O. NO. CSS 94849, WO 13848JOB NAME/LOCATION USARC - Cross Lanes WV006  
SERVICE REQUESTED airflow through the Condenser coil.  
WV006 CSS 94849, WO 13848

Manufacture: _____				
Model#: _____				
Serial#: _____				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested  
☐ Leak Found  
☐ Leak Repaired  
 Method: \_\_\_\_\_  
 Total Charge: \_\_\_\_\_

## WORK PERFORMED/UNIT INFO.

place. Finished cutting off the enclosure that was not needed and then started measuring for my new piece of metal, notched it out so it would slide over the unit platform. Made my piece of metal and bent it as needed then done a test fit to make sure everything lined up. Secured the new piece with sheet metal screws but also used S-Locks to help stiffen then metal. Trimmed the top piece of metal and then secured it back to the top of the unit. Picked up and cleaned up all none needed materials and disposed of them. Checked out with the customer.

## NATURE OF WORK

 Regular Service \_\_\_\_\_  
 Quoted Service \_\_\_\_\_  
 Start-up/Warranty \_\_\_\_\_  
 SPD \_\_\_\_\_  
 Contract Service \_\_\_\_\_  
 Energy Management \_\_\_\_\_

## PARTS, MATERIALS AND SUBCONTRACTED SERVICES

QTY.	PART NO.	DESCRIPTION	P.L.	VENDOR	

## SUMMARY OF TIME

SERVICE TECHNICIAN	ON SITE REG.	ON SITE O.T.	REG. TRAVEL	O.T. TRAVEL	TOTAL HRS.	MEALS	LODGING	TOLLS	MILES	OTHER

JOB COMPLETE YES \_\_\_\_\_ NO \_\_\_\_\_ EXPLAIN \_\_\_\_\_

SIGNATURE \_\_\_\_\_

Customer Representative