

CASTO TECHNICAL SERVICES, INC.

SERVICE REPORT

DATE 2024 6 20 ARRIVAL TIME 8:30am DEPARTURE TIME 2:30pm JOB/TCK. NO. 209429CUSTOMER P.O. NO. CSS#98082JOB NAME/LOCATION USARC - Bluefield WV005SERVICE REQUESTED (8) Investment is to replace the CFM and Fan Blade on Daikin VRF CU-1 (M# REYQ96; S# A000151) that serves

Manufacture: <u>Daikin</u>				
Model#: <u>REYQ96PBTJ</u>				
Serial#: <u>A000151</u>				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested☐ Leak Found☐ Leak Repaired

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO.

Arrived on site checked in with customer. Went to CU-1. Turned unit off and unwired condenser fan from inverter board. Removed condenser fan motor and blade then installed new motor and blade. Reinstalled cover. Ohmed new motor to make sure it read correctly. Turned unit back on and hooked up laptop. No alarms were present. Overrode all indoor units to call for cooling and watched pressures and temperatures on computer. Checked controller inside to make sure H7 alarm had cleared. Released override from my computer and let unit run under its own power for a while to make sure everything ran correctly. Let customer know I was finished and got signature for COW form.

NATURE OF WORK

Regular Service _____

Quoted Service _____

Start-up/Warranty _____

SPD _____

Contract Service _____

Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

QTY.	PART NO.	DESCRIPTION	P.L.	VENDOR	
1		Shipping & Handling		Mason	242934
1		2097860 fan blade		Mason	242934
1		2534435 Motor		Mason	242934

SUMMARY OF TIME

SERVICE TECHNICIAN	ON SITE REG.	ON SITE O.T.	REG. TRAVEL	O.T. TRAVEL	TOTAL HRS.	MEALS	LODGING	TOLLS	MILES	OTHER
1346 Eli Ayers	6		2		8					

JOB COMPLETE YES X NO _____ EXPLAIN _____

SIGNATURE _____

Customer Representative