

## CASTO TECHNICAL SERVICES, INC.

## SERVICE REPORT

DATE 2025 2 28 ARRIVAL TIME 8:30am DEPARTURE TIME 2:30pm JOB/TCK. NO. 215724CUSTOMER P.O. NO. FEMS 2965965JOB NAME/LOCATION USARC - Bluefield WV005SERVICE REQUESTED (68) Investment is to Recover Refrigerant, replace the Capillary Tube, Pull a Vacuum, and Recharge Daikin VRF

Manufacture: <u>Daikin</u>				
Model#: <u>REYQ144PBTJ</u>				
Serial#: <u>A000243</u>				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested

☐ Leak Found

☐ Leak Repaired

Method: \_\_\_\_\_

Total Charge: \_\_\_\_\_

## WORK PERFORMED/UNIT INFO.

Stopped at United to pick up another 25 pounds of refrigerant for job. Arrived on site checked in with customer. Went to CU-2 to check vacuum progress. Unit had pulled down to 90 microns. Charged unit with 75 pounds of r410a. Hooked up with the service checker, placed unit back in normal operation and went inside to controller to turn it on. Monitored CU-2 and CU-1 for the rest of the time to make sure they ran correctly. Right side condenser fan motor on CU-2 has bearings that are going bad, but unit is still running. Will quote to replace motor. Cleaned up trash and let customer know I was finished.

## NATURE OF WORK

Regular Service \_\_\_\_\_

Quoted Service \_\_\_\_\_

Start-up/Warranty \_\_\_\_\_

SPD \_\_\_\_\_

Contract Service \_\_\_\_\_

Energy Management \_\_\_\_\_

## PARTS, MATERIALS AND SUBCONTRACTED SERVICES

QTY.	PART NO.	DESCRIPTION	P.L.	VENDOR	
3		R-410A refrigerant		United	250196
1		Shipping & Handling		Mason	249114
1		Compressor		Mason	249114
1		Shipping & Handling		Mason	249114
1		Capillary Tube		Mason	249114

## SUMMARY OF TIME

SERVICE TECHNICIAN	ON SITE REG.	ON SITE O.T.	REG. TRAVEL	O.T. TRAVEL	TOTAL HRS.	MEALS	LODGING	TOLLS	MILES	OTHER
1346 Eli Ayers	6		2		8					

JOB COMPLETE YES X NO \_\_\_\_\_ EXPLAIN \_\_\_\_\_

SIGNATURE \_\_\_\_\_

Customer Representative