

CASTO TECHNICAL SERVICES, INC.

SERVICE REPORT

DATE 2025 4 29 ARRIVAL TIME 8:00AM DEPARTURE TIME 5:30PM JOB/TCK. NO. 216715CUSTOMER P.O. NO. 0000534JOB NAME/LOCATION USARC - Abingdon VA001SERVICE REQUESTED (32) Investment is to replace the Circuit Breaker, Motor Starter, and Rewire Daikin AHU (M# CAH008; S#

Manufacture: <u>Daikin</u>				
Model#: <u>CAH008GMAM</u>				
Serial#: <u>FB0U240401757</u>				
Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

☐ Leak Tested☐ Leak Found☐ Leak Repaired

Method: _____

Total Charge: _____

WORK PERFORMED/UNIT INFO.

Arrived and removed breaker box cover and removed bad breaker and installed new 30amp breaker also got wiring ready to pull out so we can pull new wire in and then installed new motor starter and wired it up and pulled new wire from starter to AHU there was 4 slices in it we made it a home run put power on it and checked its operation and found that all was fine and DX cooling was on and bldg. was cooling down.

NATURE OF WORK

Regular Service _____

Quoted Service _____

Start-up/Warranty _____

SPD _____

Contract Service _____

Energy Management _____

PARTS, MATERIALS AND SUBCONTRACTED SERVICES

QTY.	PART NO.	DESCRIPTION	P.L.	VENDOR	
500		WCUTHHN10STRGN GREEN WIRE		State	251280
500		WCUTHHN10STRBE BLUE WIRE		State	251280
500		SCUTHHN10STRRD RED WIRE		State	251280
500		WCUTHHN10STRBK BLACK WIRE		State	251280
1		SQDQ0B330 CIRCUIT BREAKER		State	251280
1		A-B509B0DA2G STARTER		State	251280

SUMMARY OF TIME

SERVICE TECHNICIAN	ON SITE REG.	ON SITE O.T.	REG. TRAVEL	O.T. TRAVEL	TOTAL HRS.	MEALS	LODGING	TOLLS	MILES	OTHER
58 Mark Bass	8	1			9					
1378 Joseph Harrah	8	1			9					

JOB COMPLETE YES X NO _____ EXPLAIN _____

SIGNATURE _____

Customer Representative