

CASTO TECHNICAL SERVICES, INC.

## SERVICE REPORT

DATE 2024 7 31 ARRIVAL TIME 9:00

DEPARTURE TIME 10:00

JOB/TICK NO 211142

CUSTOMER P.O. NO. CSS94603

**JOB NAME/LOCATION** USARC - Beaver WV002

**SERVICE REQUESTED** OMS 2 AHU's need repaired or replaced. w/o 16383

Manufacture:			
Model#:			
Serial#:			
Refrigerant Added:	Qty	lb	oz
Refrigerant Removed:	Qty	lb	oz

- Leak Tested
- Leak Found
- Leak Repaired

Method: \_\_\_\_\_

Total Charge: \_\_\_\_\_

**WORK PERFORMED/UNIT INFO**

Got on site and checked in with customer. Checked in with Amy to see what AHU's needed looked at replacing. Was the hallway mechanical room AHU system. AHU, condenser, and VAV's. I got the info off of the AHU and then got ahold of Matt to let him know he's gonna need to stop by with R&I to check this job out given the scope of work. Packed up and left after that. Amy called a little while later and said it was actually the shop AHU's that needed looked at. I advised her i'd swing back by tomorrow to check it out.

**NATURE OF WORK**

Regular Service \_\_\_\_\_

Quoted Service \_\_\_\_\_

Start-up/Warranty \_\_\_\_\_

SPD \_\_\_\_\_

Contract Service \_\_\_\_\_

Energy Management \_\_\_\_\_

**PARTS, MATERIALS AND SUBCONTRACTED SERVICES**

## **SUMMARY OF TIME**

**JOB COMPLETE**

YES \_\_\_\_\_ NO \_\_\_\_\_ EXPLAIN \_\_\_\_\_

**SIGNATURE** \_\_\_\_\_

### **Customer Representative**