

CASTO TECHNICAL SERVICES, INC.

## SERVICE REPORT

DATE 3/17/2023 ARRIVAL TIME DEPARTURE TIME JOB/TCK. NO. 193283

CUSTOMER P.O. NO. CSS# 91542

**JOB NAME/LOCATION** USARC - New River Valley Memorial VA012

**SERVICE REQUESTED** (7) *Investment is labor and material to cut the elbows out, put in new piping, and repair the leaking piping.*

Manufacture: \_\_\_\_\_  
Model#: \_\_\_\_\_  
Serial#: \_\_\_\_\_

Refrigerant Added:	Qty	lb	oz	TYPE
Refrigerant Removed:	Qty	lb	oz	TYPE

- Leak Tested
- Leak Found
- Leak Repaired

Method: \_\_\_\_\_

Total Charge: \_\_\_\_\_

**WORK PERFORMED/UNIT INFO**

I loaded PVC pipe and then loaded the fittings into truck then drove to beckly and met Shawn then cut the pvc in half and put all material in his van then left and drove to another job site.

**NATURE OF WORK**

Regular Service \_\_\_\_\_

Quoted Service \_\_\_\_\_

Start-up/Warranty \_\_\_\_\_

SPD \_\_\_\_\_

Contract Service \_\_\_\_\_

Energy Management \_\_\_\_\_

**PARTS, MATERIALS AND SUBCONTRACTED SERVICES**

## **SUMMARY OF TIME**

JOB COMPLETE YES  NO  EXPLAIN \_\_\_\_\_

**SIGNATURE** \_\_\_\_\_

### **Customer Representative**