

Date: 12-12-24

Region: 4C

FEMS/CSS No.: 94492

FAC ID: VA001

Maximo WO No.: 17400

Asset #:

Priority: 3



Original Work Request:

The training facility has several areas where the mortar joints have deteriorated and is allowing moisture to get behind the brick veneer. Ticket is to survey entire exterior of the facility and correct these deficiencies by repointing and caulking as needed.

Description of Repairs Needed:

Inspect the building for areas that need repaired and what is required to repair them.

Labor:

| | Labor Hrs | Labor Rate | Total |
|----------------|-----------|------------|-----------|
| Tech (1) | 4 | \$ 83.00 | \$ 332.00 |
| Travel Expense | 1 | \$ 75.00 | \$ 75.00 |
| | | | \$ - |

Material List:

| | Quantity | Cost | Total |
|--|----------|------|-------|
| | | \$ - | |
| | | \$ - | |
| | | \$ - | |
| | | \$ - | |
| | | \$ - | |
| | | \$ - | |
| | | \$ - | |

Equipment List:

| | Quantity | Cost | Total |
|--|----------|------|-------|
| | | \$ - | |
| | | \$ - | |
| | | \$ - | |

PM WO History:

| |
|--|
| |
| |

Estimate Summary:

| Labor | Material | Equipment |
|----------|----------|-----------|
| \$407.00 | \$0.00 | \$0.00 |

| Sub Total | G&A 12% | Fee 6% | Total Estimate |
|-----------|---------|---------|----------------|
| \$407.00 | \$48.84 | \$24.42 | \$480.26 |