

Additional Funding Request

Submitted: 07/22/2021

VA002 - GATE	CSS # 31582 WO# 14551								
Description of Repairs	As per our diagnosis performed on 7/15/2021, it was discovered the Low Voltage Power Supply needs to be replaced. Additional issues may be present in the Gate Operator causing malfunction but cannot be diagnosed at this time until Power Supply is replaced. LoCurrent Systems is pleased to provide a quotation to replace (1) Low Voltage Power Supply at the Lieber Center Alexandria VA002 USARC.								
Original SC Investigative Diagnosis	\$450.00								
Diagnosis: Initial Work Order	Main Gate not working -No power to control board Mice in panel								
Explanation of Additional Costs for Repairs	N/A								
Additional Material Cost to Perform Repairs	<p>Materials: \$144.00</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;">Parts (See detail in quote)</td> <td style="text-align: center; padding: 2px;">1</td> <td style="text-align: center; padding: 2px;">1</td> <td style="text-align: right; padding: 2px;">\$ 144.00</td> </tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL	Parts (See detail in quote)	1	1	\$ 144.00
ITEM	QUANTITY	UNIT PRICE	TOTAL						
Parts (See detail in quote)	1	1	\$ 144.00						
Additional Labor Cost to Perform Repairs	<p>Labor: \$600.00 8 hours each/Rate \$75 per hour = \$600.00</p>								
Total Cost of Repair	\$1,194.00								