

**Region:** 5

**Location:** VA002

**CSS #** 613

**Maximo Work Order No.:** 17764

**Asset #:** NA

**Date Issued:** 06/24/22

**Original Description:** FCU#4 , FCU#9 , FCU#18 , FCU#25 , FCU#34 , FCU#35 are in alarm and need to be checked

**Repairs Needed:**

After diagnosis we found a York unit needs a custom programmed controller.

S&S will accompany a controls technician from Havtech to determine if we can upload the original program.

**RS Means Line Buildup and Labor Summary (Data Version 2017, Q4):**

Quantity	Line Item Number	Description	Labor Hours	Labor Rate/Hr	Materials	Equipment	Total
--	NA	HAVTECH Controls Tech	--	--	\$2,304.00	--	\$2,304.00
--	NA	S&S Diagnostic	6.25	\$80.00	--	--	\$500.00
--	NA	HVAC Labor	10	\$100.00	--	--	\$1,000.00

**Estimate Summary:**

Labor Hours	Labor Cost	Material Cost	Equipment Lift	Total Cost	CE Factor	Total Estimate
16.25	\$1,500.00	\$2,304.00		\$3,804.00	106%	<b>\$4,032.24</b>