

## Additional Funding Request

Submitted: 6.1.2020

<b>VA002</b> – FCU# 23 - faulty temp sensor	<b>CSS #25258 WO# 12324</b>			
Description of Repairs	FCU#23 has a faulty discharge air temperature sensor that needs to be replaced			
Original SC Investigative Diagnosis Fee	<b>\$100.00</b>			
Diagnosis: Initial Work Order	S&S was onsite preforming PMs and diagnosed FCU# 23 has a faulty temp sensor. S&S will remove and replace the temperature sensor and filters. S&S will then perform a system check to ensure everything is running properly.			
Explanation of Additional Costs for Repairs	N/A			
Additional Material Cost to Perform Repairs	<b>Materials: \$270.74</b>			
	<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>
	Temperature Sensor/3435	1	\$5.99	\$5.99
	Filters/ RPE-48-BD	4	\$51.06	\$204.24
	Tax	1	\$10.51	\$10.51
	Shipping	1	\$50.00	\$50.00
Additional Labor Cost to Perform Repairs	<b>Labor: \$900.00</b> HVAC Labor Tech/9 hours/Rate \$100.00 per hour = \$900.00			
<b>Total Cost of Repair</b>	<b>\$1,270.74</b>			