

## Additional Funding Request Corrective Maintenance from PM

<b>VA002 - parking lot light blinking</b>	<b>Maximo WO#6013 Asset # 2230 CSS# pending</b>
Description of Repairs	Led light replacement- asset #2230 -#09 – right lamp blinking
Diagnosis: Initial Work Order	<p>-S&amp;S will remove and replace the pole light driver - S&amp;S will provide truck with lift -This work is to be completed during the normal business hours of M-F, 7am-3pm.</p> <p>-This repair is based off customer description of issue.</p>
Explanation of Additional Costs for Repairs	<p>S&amp;S will remove and replace the pole light driver -S&amp;S will provide truck with lift -This work is to be completed during the normal business hours of M-F, 7am-3pm.</p> <p>-This repair is based off customer description of issue.</p>
Additional Labor Cost to Perform Repairs	<b>Labor Total: \$400.00</b> 1 electrician / 4 hours / \$100.00 per hour
Additional Material Cost to Perform Repairs	<b>Materials Total: \$132.17</b> PN: XI150C105V140CNF1M / QTY: 1 / \$125.88 Tax: \$6.29
Bucket lift truck cost	\$300.00
<b>Total cost</b>	<b>\$ 832.17</b>
Minus \$250 cost of PM	\$582.17 after \$250 PM credit
Total Cost of Repair	\$582.17