

## Additional Funding Request

Submitted: 1/21/2020

<b>VA002 – PTAC unit, Room 111</b>	<b>CSS #20965 - WO#11554 – Asset 2189</b>			
Description of Repairs	PTAC Room 111 - reported unit has a leak.			
Original SC Investigative Diagnosis Fee	<b>\$250.00</b>			
Diagnosis: Initial Work Order	Unit needs to be checked for full operation, clean condensate line.			
Explanation of Additional Costs for Repairs	N/A			
Additional Material Cost to Perform Repairs	<b>Materials: \$428.45</b>			
	<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>
	Transformer/ 226968	1	\$57.77	\$57.77
	Actuator/ 226970	1	\$87.60	\$87.60
	Relay/ 55835	3	\$20.26	\$60.78
	Base/ 55142	3	\$19.68	\$59.04
	Shipping	1	\$150.00	\$150.00
	Tax	1	\$13.26	\$13.26
Additional Labor Cost to Perform Repairs	<b>Labor: \$1,000.00</b> Labor Tech/10 hours/Rate \$100.00 per hour = \$1,000.00			
<b>Total Cost of Repair</b>	<b>\$1,678.45</b>			