

## Additional Funding Request

Submitted: 1/15/2020

<b>VA002</b> – gate reader	<b>CSS #23255 WO#11568</b>			
Description of Repairs	Gate is not opening all the way on its own.			
Original SC Investigative Diagnosis	<b>NA</b>			
Diagnosis: Initial Work Order	LoCurrent has been out to diagnose & found that the issue was the reader; it was intermittently failing; replacing reader on gate.			
Explanation of Additional Costs for Repairs	N/A			
Additional Material Cost to Perform Repairs	<b>Materials: \$1,250.00</b>			
	<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>
	Veridt Multimode Biometric Reader – Part #900W2030	1	\$1,450.00	\$1,450.00
	Core Charge	1	(\$200.00)	(\$200.00)
	<b>TOTAL</b>			<b>\$1,250.00</b>
Additional Labor Cost to Perform Repairs	<b>Labor: \$600.00</b> 2 Labor Techs/4 hours each/Rate \$75.00 per hour = \$600.00			
<b>Total Cost of Repair</b>	<b>\$1,850.00</b>			