



CERTIFICATE OF BOILER OR PRESSURE VESSEL INSPECTION

| | | | |
|-----------------------|--------------|------------------------|-----------|
| Boiler or Vessel No.: | SN E17Q21809 | State or Standard No.: | ASSET2259 |
|-----------------------|--------------|------------------------|-----------|

This is to certify that the here in-described boiler/pressure vessel inspected by

ARISE

| |
|--|
| on: 10/29/2018 |
| may be operated at a pressure not to exceed 50 pounds per square inch. |

| | | | |
|--------------|--|--------------|----------|
| Name of User | US Army Reserve Region 4 Zone C9-VA009 | | |
| Address | 3502 Bennetts Creek Park Rd Suffolk, VA 23435-2375 | | |
| Location | Mech Rm | | |
| Type | Water Tube | Manufacturer | MUNCHKIN |
| | | Date Mfg. | 2009 |

Certificate expires 10/29/2020 or upon the cancellation of the company's insurance coverage on the object, whichever occurs first.

INSPECTIONS

| TYPE OF INSPECTION | DATE | INSPECTOR | COMMISSION NUMBER |
|--------------------|------------|-------------------|-------------------|
| External | 10/29/2018 | Micheal A. Morgan | 12262 |
| | | | |
| | | | |

This document should be posted in a conspicuous place, accessible to concerned individuals and located in the general area of the boiler or pressure vessel.



CERTIFICATE OF BOILER OR PRESSURE VESSEL INSPECTION

| | | | |
|-----------------------|-------------|------------------------|-----------|
| Boiler or Vessel No.: | SNF01Q24274 | State or Standard No.: | ASSET2260 |
|-----------------------|-------------|------------------------|-----------|

This is to certify that the here in-described boiler/pressure vessel inspected by

ARISE

| |
|--|
| on: 10/29/2018 |
| may be operated at a pressure not to exceed 50 pounds per square inch. |

| | | | |
|--------------|--|--------------|----------|
| Name of User | US Army Reserve Region 4 Zone C9-VA009 | | |
| Address | 3502 Bennetts Creek Park Rd Suffolk, VA 23435-2375 | | |
| Location | Mech Rm | | |
| Type | Water Tube | Manufacturer | MUNCHKIN |
| | | Date Mfg. | 2009 |

Certificate expires 10/29/2020 or upon the cancellation of the company's insurance coverage on the object, whichever occurs first.

INSPECTIONS

| TYPE OF INSPECTION | DATE | INSPECTOR | COMMISSION NUMBER |
|--------------------|------------|-------------------|-------------------|
| External | 10/29/2018 | Micheal A. Morgan | 12262 |
| | | | |
| | | | |

This document should be posted in a conspicuous place, accessible to concerned individuals and located in the general area of the boiler or pressure vessel.



Grand Bay I
7000 South Edgerton Suite 100
Brecksville, OH 44141-3172
Phone: (440) 740-0197
FAX: (440) 746-8957
www.ariseinc.com

November 2, 2018

Mr. Brian Leighton (e-mail)
Senior Site Supervisor
US ARMY RESERVE – REGION 4 ZONE C9
International Support Group
9000 Sheridan Street Suite 172
Pembroke Pines, FL 33024-8803
bleighton@internationalsupportgroup.com

RE: **Non-Jurisdictional Inspection**
US Army Reserve Regions 4 Zone C9
Location No. VA009
3502 Bennetts Creek Park Road
Suffolk, VA 23435-2375
File No. 6082.0017

Dear Mr. Leighton:

A Non-Jurisdictional Inspection was performed at the captioned location on October 29, 2018, in the company of SFC Hill, for the purpose of issuing ARISE Certificates of Inspection. The following objects were inspected:

| Manufacturer | Type of Object | Object No. | NB or Other No. | Type of Insp. |
|--------------|----------------|------------|-----------------|---------------|
| MUNCHKIN | Water Tube | ASSET2259 | SN E17Q21809 | External Cert |
| MUNCHKIN | Water Tube | ASSET2260 | SNF01Q24274 | External Cert |

The external surfaces and installed safety devices was inspected. A request was also made to review the test records of the installed safety devices, there were no records showing that the installed safety devices had been tested. It was explained that a record should be made each time the safety devices are tested and these records should be maintained.

During the external inspection the safety relief valve discharge piping was discolored from corrosion, indicating leakage of the safety relief valves. During the inspection a boiler contractor was on-sight and the finding was explained to them as what needed to be corrected before the boilers could be placed back into operation. They were making a request and awaiting approval to replace the safety relief valves.

No pressure test of any system was conducted, as they are not required for an external inspection and no code repairs was conducted on the boilers. The Low Water Cutoff, High-Limit Controller and Operating controller was not tested during the inspection, as they manufactured computer installed as per the boilers electrical diagram. Each has to be jumper out to be tested.

Prior to departure an exit interview was conducted with Sargent First Class Hill.

No violations or recommendations have been issued as a result of this inspection.

US ARMY RESERVE – REGION 4 ZONE C9
Non-Jurisdictional Inspection

10/18
6082.0017

I would like to thank you, and those members of your staff present, for your cooperation and assistance. If you should have any questions or comments regarding this inspection, please contact our Brecksville office at (440) 740-0197.

Regards,

Micheal Morgan/pm

Micheal Morgan
B & M Consultant

MM:pm

Enc.

cc: File copy