

Date: 5-30-24

Region: 4C

CSS No.: 96145

FAC ID: VA012

Maximo WO No.: 15604

Asset #:

Priority: 2



Original Work Request:

This unit is not running and needs to be serviced to identify what is causing it to shut off and repair. This is not covered under the PM currently, so they need a ticket.

Description of Repairs Needed:

Investigated and assessed that the mini-split needs new control boards installed to address the unit short cycling and shutting off.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	4	\$ 100.00	\$ 400.00
			\$ -

Material List:

	Quantity	Cost	Total
LG Main PCB Assembly (EBR83671017)	1	\$ 150.99	\$ 150.99
LG Display PCB Assembly (EBR84585201)	1	\$ 65.95	\$ 65.95
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$400.00	\$216.94	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$616.94	\$74.03	\$37.02	\$727.99