

Date: 7-21-25

Region: 4C

FEMS/CSS No.: 96473

FAC ID: VA012

Maximo WO No.: 18504

Asset #:

Priority: 2



Original Work Request:

The rear roll up door to shop stopped working. It went up but won't come down. We had to manually get it down. Last time we had door issues the vendor said it was a sensor issue. We need this fixed ASAP.

Description of Repairs Needed:

Proposal is to replace 3 set of Miller safety edge transmitters and receivers.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	3	\$ 150.00	\$ 450.00
Trip Charge	1	\$ 125.00	\$ 125.00
Tech (2) - investigation	1	\$ 150.00	\$ 150.00
Trip Charge - investigation	1	\$ 125.00	\$ 125.00

Material List:

	Quantity	Cost	Total
Wireless Transmitter (MWTA12)	3	\$ 406.00	\$ 1,218.00
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
Scissor Lift	1	\$ 350.00	\$ 350.00
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$850.00	\$1,218.00	\$350.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,418.00	\$290.16	\$145.08	\$2,853.24