

Date: 11-22-24

Region: 4C
FAC ID: VA012

FEMS/CSS No.: 2935373
Maximo WO No.: 17360

Asset #:

Priority: 2



Original Work Request:

Antifreeze pump has stopped working due to internal corrosion. It's a rotary pump and the antifreeze is causing the bearing to seize. I believe this is the second or third time this has happened with this pump and it just needs to be replaced. Recommended Contractor: Waco (540) 962-5161

Description of Repairs Needed:

Replace antifreeze pump and verify operations

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	20	\$ 92.18	\$ 1,843.60
			\$ -

Material List:

	Quantity	Cost	Total
Sampson Pump (Model DF 100)	1	\$ 1,144.78	\$ 1,144.78
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,843.60	\$1,144.78	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,988.38	\$358.61	\$179.30	\$3,526.29