

Date:

Region:

FEMS/CSS No.:

FAC ID:

Maximo WO No.:

Asset #:

Priority:



Original Work Request:

DHW Tank Pump (Gold) not working. It was discovered on site by Casto that this pump is not working and needs to be replaced.

Description of Repairs Needed:

Repair - Replace Domestic HW circulator pump and motor.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	12	\$ 138.00	\$ 1,656.00
Trip Charge	90	\$ 1.75	\$ 157.50
			\$ -

Material List:

	Quantity	Cost	Total
1BL012 Pump & Motor - ThermoFlo	1	\$ 680.40	\$ 680.40
Shipping & Handling	1	\$ 65.00	\$ 65.00
Misc Parts (shop supplies, gasket, etc)	1	\$ 90.00	\$ 90.00
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

--

Estimate Summary:

Labor	Material	Equipment
\$1,813.50	\$835.40	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$2,648.90	\$317.87	\$158.93	\$3,125.70