

Date: 5-9-2025

Region: 4C

FEMS/CSS No.: 2966390

FAC ID: VA033

Maximo WO No.: 18863

Asset #:

Priority:  3



**Original Work Request:**

The flashing over the wood soffit area has come off and needs replaced. The metal has been saved however, it is undure if the same material can be reused. Recommended contractor Tri-State Roofing

**Description of Repairs Needed:**

Proposal is for work completed to repair side metal on building. Crew was able to use the metal that came of the building and complete while on site.

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (2)	8	\$ 108.25	\$ 866.00
			\$ -
			\$ -

**Material List:**

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	

**Equipment List:**

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

**PM WO History:**


**Estimate Summary:**

Labor	Material	Equipment
\$866.00	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$866.00	\$103.92	\$51.96	\$1,021.88