

Date:

Region:

FEMS/CSS No.:

FAC ID:

Maximo WO No.:

Asset #:

Priority:



Original Work Request:

No heat in the OMS. The propane vent (regulator) on the side of the OMS building is leaking and needs replaced. Pics and video received from the FC. Currently the propane tanks are shut off on the tanks.

Description of Repairs Needed:

Labor for contractor to investigate and retrieve information on replacing the propane regulator that feeds the building. Will provide customer with quote.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	3.5	\$ 138.00	\$ 483.00
Trip Charge	1	\$ 131.25	\$ 131.25
			\$ -

Material List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	
		\$ -	

Equipment List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$614.25	\$0.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$614.25	\$73.71	\$36.86	\$724.82