

Date: 10/5/2023

Region: 4C
FAC ID: VA039

CSS No.: 94671
Maximo WO No.: 14101

Asset #: []

Priority: 3



Original Work Request:

Post inspection crane repair to to replace pins mounting hoist to trolley and replace/repair squeaking discs glazed over. Correct collectors that are out of alignment, worn/dead spots. Repair recommended by U.S. Crane during inspection in July

Description of Repairs Needed:

Address items identified during annual inspection services as needing to be replaced. Will require lift to access crane. Inspection report attached.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	1	\$ 1,870.00	\$ 1,870.00
			\$ -

Material List:

	Quantity	Cost	Total
Service Estimate (rplc pins, correct alignment, rplc discs)	1	\$ 3,500.00	\$ 3,500.00
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
lift	1	\$ 1,825.00	\$ 1,825.00
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$1,870.00	\$3,500.00	\$1,825.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$7,195.00	\$863.40	\$431.70	\$8,490.10