

Date: 12-5-24

Region: 4C

FAC ID: VA039

FEMS/CSS No.: 2966015

Maximo WO No.: 17367



Asset #:

Priority: 3

Original Work Request:

Vault motion sensors are supposed to be independent from one another and where they are not this is a physical security violation given during recent inspection.

Description of Repairs Needed:

Rewire vault motion sensors

Labor:

	Labor Hrs	Labor Rate	Total
Tech (2)	32	\$ 95.00	\$ 3,040.00
Travel charge	1	\$ 100.00	\$ 100.00
			\$ -

Material List:

	Quantity	Cost	Total
Motion Sensors	2	\$ 156.00	\$ 312.00
DSC Zone Expander	1	\$ 80.00	\$ 80.00
Misc Materials, cabeling, etc	1	\$ 250.00	\$ 250.00
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$3,140.00	\$642.00	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$3,782.00	\$453.84	\$226.92	\$4,462.76