

Additional Funding Request

VA049	CSS# 27696 WO# 13300 Asset# NA							
Description of Repairs	Install customer provided X-10 Locks *Safe/ Vault must be open for access to remove existing install							
Diagnosis: Initial Work Order	The unit has purchased new digital locks and need to have the old ones removed and new ones installed.							
Diagnostic Fee	\$ 0							
Additional Labor Cost to Perform Repairs	\$ 2160.00 Note: Job is complete labor							
Additional Material Cost to Perform Repairs	\$ 0 <table border="1" style="width: 100%; text-align: center;"> <tr> <td>Parts w/tax</td> <td>0</td> <td>0</td> <td>0</td> </tr> </table>				Parts w/tax	0	0	0
Parts w/tax	0	0	0					
Total Cost of Repair	\$ 2160.00							



6318 Reisterstown Rd
Baltimore MD 21215
410-764-2001
Billing2@ampmlock.com

Estimate

ESTIMATE#	1304
DATE	11/24/2020
PO#	CSS 27696 WO 13300

CUSTOMER	SERVICE LOCATION
Tidewater PM 6002 Strathmore Road Richmond VA 23234 (703) 738-5301	Tidewater PM 6700 Strathmore Road Richmond VA 23237 (703) 738-5301

Estimate				
Description	Qty	Rate	Total	
Service Call	1.00	150.00	150.00	
Labor	8.00	120.00	960.00	
Extended Travel Time				
Labor	3.00	350.00	1,050.00	
Install Customer Provided X-10 Locks				

*Safe/Vault must be open for access to remove existing and install

CUSTOMER MESSAGE
Advanced Security Safe & Lock's One Year Warranty on recalls only covers parts and services/labor when the part is provided by Advanced Security Safe & Lock. Service/labor on parts not provided by Advanced Security Safe & Lock or if the parts have passed the one year warranty time period are NOT covered under Advanced Security Safe & Lock's One Year Warranty.
PRINT NAME: _____
DATE: _____
Terms: Non-Refundable 50% deposit and 50% due upon completion terms. Subject to late penalties.

Estimate Total: \$2,160.00