

## Brenda Gerold

---

**From:** Richard Hicks  
**Sent:** Thursday, May 7, 2020 7:08 AM  
**To:** Brenda Gerold  
**Subject:** FW: CSS 24864 WO 11779 Additional Work Required  
**Attachments:** IMG\_0656.jpg; IMG\_0659.jpg; IMG\_0658.jpg

**Follow Up Flag:** Follow up  
**Flag Status:** Flagged

Please upload to 11779

---

**From:** Adam Colopy <adam.colopy@tideh2o.net>  
**Sent:** Wednesday, May 6, 2020 3:59 PM  
**To:** Grenier, Scott Anthony CIV USARMY 99 RD (USA) <scott.a.grenier.civ@mail.mil>  
**Cc:** Anderson, Mark S CIV USARMY 80 TNG CMD (USA) <mark.s.anderson7.civ@mail.mil>; Devlin, Thomas J CIV USARMY CENAP (US) <Thomas.J.Devlin@usace.army.mil>; Richard Hicks <richard.hicks@cmimgmt.com>; Tina Lee <tina.lee@tideh2o.net>  
**Subject:** CSS 24864 WO 11779 Additional Work Required

Scott,

Moore's was onsite working on CSS 24864 today at VA049. Once the insulation was cut back they found that the pipe was severely pitted and corroded (See attached pictures) due to a roof leak resulting in water getting behind the insulation and running down the piping. Approximately 15 feet of pipe running up through the roof needs to be replaced. Tom has already gave the go ahead for Moore's to acquire the additional materials and return tomorrow morning to complete (note the chiller will be down in the meantime). Moore's cannot however repair the roof as part of their scope so can you please issue a new CSS ticket for the roof repair and we will get a roofer out to investigate as soon as possible?

Let me know if you have any questions or concerns.

Thanks,

**Adam Colopy, FMP**  
*Mid-West Regional Operations Manager*  
**TIDEWATER, INC.**

---

[adam.colopy@tideh2o.net](mailto:adam.colopy@tideh2o.net)  
3761 Attucks Drive  
Powell, OH 43065

**C:** 740-819-6207  
**F:** 410-997-8713

[www.tideh2o.net](http://www.tideh2o.net)