

DAILY WORK ORDER

50 55th Street
Pittsburgh, PA 15201
www.mckamish.com
dispatch@mckamish.com
24 Hour Service: 412.781.6363

Customer Name: US ARMY
Customer PO#: CSS 14597
Work Location: USARMY-USARC-TRAINING CTR
99 SOLDIER LANE
MOON TOWNSHIP, PA 15108

Work Date: July 19, 2018
Caller Name: STEVE MILLER
Work Order ID: 16212

Problem Reported by Customer

MOTOR FOR EXHAUST FAN #5 DOES NOT TURN ON WHEN START SIGNAL IS RECEIVED. 3RD FL M LATRINE.
CSS 14597 WO 5151 PA166

Description of Work Performed

Date	Technician
07/19/2018	MICHAEL J HORZEMPA
Inspected exhaust fan #5 tag# 2460 Found motor faulty	

Recommended Repair

Date	Technician
07/19/2018	MICHAEL J HORZEMPA
Replace exhaust fan motor	


Time Log for MICHAEL J HORZEMPA

Date	Regular Time	Overtime	Double Time
07/19/2018	1.50	0.00	0.00
Total:	1.50	0.00	0.00

Customer Signature:



Printed Name: STEVE MILLER,
Recipients Email:



Dayton

Belt Drive Fan And Blower Mot

**Mod
No**

6K570K

CE

SI

2446

HP: 1/2

VOLTS: 115

AMPS: 6.6

RPM: 1725

DEUTY: Continuous

SHA: 2A

ASA CODE: N

THERMALLY PROTECTED: Auto
SLEEPER MODE: After 3 Years Normal Service, Reoil
THE LIFE SPAN: With 10 Doses of SW30 Oil

PH: 1

H2: 60

FR: 48Y

INS CL: B

AMB: 40°C

SF: 1.35

ENCL: ODP

Note

Read Instructions and Safety Information on Motor Before Connecting
the Motor to Power Source. Use Tools in Proper Order and Sequence.
DO NOT CONNECT MOTOR TO POWER SOURCE UNTIL
INSTRUCTIONS ARE READ AND UNDERSTOOD.

**Lead Connection
Disconnect Power Before Making
Connections or Change**

CW SHAFT END

RED — 5

BLACK — 2

4 — LINE 1

1

BL

RE