

Date: 11-08-23

Region: 4C
FAC ID: WV005

CSS No.: 95615
Maximo WO No.: 14294

Asset #:

Priority: 3



Original Work Request:

Additional repairs for Daikin unit in Server Rm that has error code. Additional work not included in orginal ticket to replace sensor.

Description of Repairs Needed:

Discovered dead mouse on power lines and replace thermistor sensor. Original repair replaced A2P thermistor (item #1808702). The additional repair will replace thermistor sensor (item #228765), which is a different and additional sensor from the original approved repair. Tech will monitor on site to ensure unit is operational before leaving.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	8	\$ 110.00	\$ 880.00
			\$ -

Material List:

	Quantity	Cost	Total
Temp Sensor (#228765)	1	\$ 174.94	\$ 174.94
Fuel surcharge	1	\$ 20.00	\$ 20.00
Service Charge	1	\$ 5.00	\$ 5.00
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$880.00	\$199.94	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,079.94	\$129.59	\$64.80	\$1,274.33