

Date: 7/5/2023

Region: 4C
FAC ID: WV006

CSS No.: 93841
Maximo WO No.: 13383

Asset #:

Priority: 3



Original Work Request:

Second floor roof top unit disconnect has bad connection. Disconnect old and becoming worn out, need replacing. New disconnect needs to be 3 PH, 240V, 100A rated for outdoor use

Description of Repairs Needed:

Lockout/Tagout power supply and remove current disconnect from roof top unit and replace with new.

Labor:

	Labor Hrs	Labor Rate	Total
1 Tech	2.5	\$ 100.00	\$ 250.00
			\$ -

Material List:

	Quantity	Cost	Total
C-HDG323URB SftySW100A, 240V, 3PNF NEMA 3R	1	\$ 457.32	\$ 457.32
Shipping/Handling	1	\$ 35.00	\$ 35.00
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

Equipment List:

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$250.00	\$492.32	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$742.32	\$89.08	\$44.54	\$875.94