

Date: 4-18-24

Region: 4C
FAC ID: WV006

CSS No.: 97363
Maximo WO No.: 15586

Asset #: multiple

Priority: 3



Original Work Request:

While performing PM on exhaust fans, CMI found 5 motors bad and need replaced.

Description of Repairs Needed:

Replace exhaust fan motors discovered during PM. Reviewed work order with AFOS and determined only four (4) need replacing instead of five. Assets identified for replacement include: 3566, 3581, 3489, and 3564.

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	8	\$ 100.00	\$ 800.00
			\$ -

Material List:

	Quantity	Cost	Total
Downblast Vent, Direct Drive 8-1/4 (5DVR5)	2	\$ 428.26	\$ 856.52
Supply Vent, 12" (4YC92)	1	\$ 801.59	\$ 801.59
Axial Downblast Roof Exhaust Fan, 1/8HP, 10" (4YC86)	1	\$ 788.00	\$ 788.00
Miscellaneous (consumables)	1	\$ 25.00	\$ 25.00
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

Equipment List:

	Quantity	Cost	Total
		\$ -	\$ -
		\$ -	\$ -
		\$ -	\$ -

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$800.00	\$2,471.11	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$3,271.11	\$392.53	\$196.27	\$3,859.91