

Date:

Region:

CSS No.:

FAC ID:

Maximo WO No.:

Asset #:

Priority:



Original Work Request:

The roof in the back hallway of the training building has a bad leak and water is pooling in the floor. We need the area investigated to find the area needing repaired.

Description of Repairs Needed:

Inspected leak area around the HVAC unit and found a total of five holes. Three holes caused by screws sticking up and penetrating EPPM two holes were punctures. Cleaned and repaired all issues

Labor:

	Labor Hrs	Labor Rate	Total
Tech (1)	3.5	\$ 100.00	\$ 350.00
			\$ -

Material List:

	Quantity	Cost	Total
Roofing caulk	2	\$ 28.74	\$ 57.48
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

Equipment List:

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$350.00	\$57.48	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$407.48	\$48.90	\$24.45	\$480.83