

Date:

Region:

FEMS/CSS No.:

FAC ID:

Maximo WO No.:

Asset #:

Priority:



**Original Work Request:**

Repair rollup door bracket. The rollup door of the wash bay motor bracket needs to be re-endorsed and/or replaced with a heavy duty bracket.

**Description of Repairs Needed:**

Disconnect and remove operator to repair and weld operator bracket. Reinstall and reconnect operator to door.

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (2)	8	\$ 155.53	\$ 1,244.22
			\$ -
			\$ -

**Material List:**

	Quantity	Cost	Total
Flat Steel & 14G Plt	1	\$ 162.80	\$ 162.80
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-
		\$	-

**Equipment List:**

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

**PM WO History:**


**Estimate Summary:**

Labor	Material	Equipment
\$1,244.22	\$162.80	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$1,407.02	\$168.84	\$84.42	\$1,660.28