

Date: 7/21/2023

Region: 4C
FAC ID: WV007

CSS No.: 93273
Maximo WO No.: 13043

Asset #:

Priority: 3



Original Work Request:

The second set of lights on the left side of ceiling are flashing and not operating correctly, it appears like the driver is going bad. This light is in the 1st Brigade Conference Rm 205 on second floor. The light doesn't do this all the time, it comes and goes.

Description of Repairs Needed:

Replace two panel lights that are flashing intermittently.

Labor:

	Labor Hrs	Labor Rate	Total
1 Tech	2	\$ 100.00	\$ 200.00
			\$ -

Material List:

	Quantity	Cost	Total
C-Lite Gen C 2x4 Flat Panel 2750 lumens, 4000K (# C-TR-C-FP24-37L-40K-WH)	2	\$ 58.97	\$ 117.94
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -

Equipment List:

	Quantity	Cost	Total
		\$ -	
		\$ -	
		\$ -	

PM WO History:

Estimate Summary:

Labor	Material	Equipment
\$200.00	\$117.94	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$317.94	\$38.15	\$19.08	\$375.17