

Date:

Region:

CSS No.:

FAC ID:

Maximo WO No.:

Asset #:

Priority:



**Original Work Request:**

We have 6 out of the 8 dampers on the HVAC system not working, this is causing the build controls not to supply the correct air mixture throughout the facility. Recommended Contractor: Casto

**Description of Repairs Needed:**

Investment is for labor to troubleshoot the outside air dampers and outside air duct for AHU-3, troubleshoot communication issues between 580 and expansion module1 on AHU-1, replace the actuators on the outside air dampers for AHU-4, and replace the motor on the exhaust fan that serves the Mechanical Rm.

**Labor:**

	Labor Hrs	Labor Rate	Total
Tech (2)	28	\$ 132.00	\$ 3,696.00
Trip Charge	50	\$ 1.75	\$ 87.50

**Material List:**

	Quantity	Cost	Total
Motor - Johnstone Parkersburg	1	\$ 228.84	\$ 228.84
AFB24-SR Damper actuator - Belimo	3	\$ 389.64	\$ 1,168.92
Shipping & Handling	1	\$ 243.00	\$ 243.00
		\$	-
		\$	-
		\$	-
		\$	-

**Equipment List:**

	Quantity	Cost	Total
		\$	-
		\$	-
		\$	-

**PM WO History:**


**Estimate Summary:**

Labor	Material	Equipment
\$3,783.50	\$1,640.76	\$0.00

Sub Total	G&A 12%	Fee 6%	Total Estimate
\$5,424.26	\$650.91	\$325.46	\$6,400.63