

CSS 16882- WV038- Routine- Both interior monitors used for exterior camera located at the main entrance of the training building are reading "no signal". Request is for vendor to troubleshoot issue and make necessary repairs to bring security camera/monitors back online.

CMI Cost Estimate							
Monitor Failure							
WV038 Romney							
CSS #16882 - CMI #7578							
Prepared By: B. Koblinsky		z					
Date: 2.11.2019							
Description	Unit	Quantity	Sub- total	6% MST	20% OHP	Total Cost	
Labor Straight Time	\$135.00	3				\$405.00	
Monitors	\$118.70	3	\$ 356.10				
Material Cost Sub-Total			\$ 356.10				
Maryland Sales Tax @ 6%				\$ 21.37			
Material OHP @ 20%					\$ 75.49		
Sub-Total			\$ 356.10	\$ 21.37	\$ 75.49	\$452.96	
Total						\$857.96	
Initial Service Call (Labor)	\$135.00	2				\$270.00	
Grand Total						\$1,127.96	