

**PROJECT ESTIMATE**

DATE: 07/07/2020

QUOTE ID: 5747  
AR CUSTOMER: CMI MANAGEMENT (#10343)  
SERVICE LOCATION: US ARMY RESERVE - CMI- SITE #NY054  
STREET: 5363 PERU STREET, ROUTE 9  
CITY: PLATTSBURGH, NY 12901

CONTACT: JOE BAYNE - CMI  
Ph:(315) 772-8801  
Fax:(315) 772-6336  
joe.bayne@cmimgmt.com  
DATE SUBMITTED: 07/07/2020  
PREPARED BY: Simpson, Heidi

DESCRIPTION: Leak Repair

SCOPE OF WORK: We were called because the AC on the split unit wasn't working. Our technician found the unit low on charge with a leak in the discharge line. This unit needs to be leak checked, repaired and recharged. This pricing includes time spent on site, labor and materials to perform this work. Please contact me with any questions. Thank you,

Heidi  
Hyde-Stone  
Mechanical Contractors  
22962 Murrock Circle  
Watertown, New York 13601  
(315) 755-2283 x238

EQUIPMENT: Make: RHEEM, M#:R0MH36AFX23, S#: EVP00182, CONDENSER, Loc: Serves first office in front of building, Eq#: 16444

ITEM	QUANTITY	UNIT PRICE	TOTAL
Labor Regular Time	5	\$110.00	\$550.00
Refrigeration Service	1	\$150.00	\$150.00
Leak Detector	1	\$10.00	\$10.00
Refrigerant (pounds)	7	\$15.00	\$105.00
Brazing Rod	1	\$8.13	\$8.13
Environmental Fee	1	\$12.00	\$12.00
Time Spent (\$50 Vehicle Charge, Labor, Valve Cores & Nuts)	1	\$435.69	\$435.69
<b>Total</b>			<b>\$1,270.82</b>

---

SIGNATURE

---

PRINT NAME

---

DATE



**PROJECT ESTIMATE**

DATE: 07/07/2020

All material is guaranteed to be as specified. All work to be completed in a workmanlike manner according to standard practices. Any alteration or deviation from the above specifications involving extra costs will be executed only upon written orders, and will become an extra charge over and above the estimate. All agreements contingent upon strikes, accidents or delays beyond our control. Our technicians are covered by New York State Workers Compensation Insurance.

QUOTE VALID FOR THIRTY (30) DAYS