



Invoice

CMI Management
Mr. Joe Bayne
5285 Shawnee Rd.
Alexandria, VA. 22312

Jun 21, 2022

RE: Saugerties Roll-up door repair
Css 1067 WO#17671

Kitchen roll-up fire-door

- Tighten loose drive sprocket bolts
- Re-Align sprocket on pocket wheel assembly
- Adjust tensioner
- Repair and re-attach fire safety control cable pulley to cmu block wall above ceiling tiles.
- Re-attach lead link to door frame.
- Lubricate tracks with silicone

5. hrs@120.00. 600.00

total labor 600.00

600.00

701 Randall Rd Ballston Spa, NY 12020 TEL 518-441-6003 FAX
518-399-5440

Email rdpostulka@verizon.net