Repair GF #4 (Trane XE90) in AMSA Bldg. Not generating heat and space temp is below 60 degrees.

Proposal to remove and replace defective board. Install a new W/R Univ Integra Furnace control silicone board.

CMI Cost Estimate								
Funding Request								
PA166 Coraopolis								
Repair GF #4 (Trane XE90) in AMSA Bldg.								
CSS #16590 - CMI # 6839								
Prepared By: J. Bayne								
12.26.18								
			Labor			**Sub**	**OHP**	
Description	**Rate**	**Hours**	**Cost**	**Material**	**Tax**	**Total**	**20%**	**Total**
1. Repair Cost								
1.1 Labor	$ 98.00	3						$ 294.00
1.2 Silicone Board					$ -	$ -	$ -	$ 136.04
1.4 Shipping								$ 24.00
Sub Total Repair Cost								**$ 454.04**
2. Initial Service Call Investigation								
2.1 Field Review at Site	$ 98.00	4						$ 392.00
Grand Total								**$ 846.04**