Additional Funding Request

VA049	CSS# 22442 WO# 11285 Asset# NA			
Description of Repairs	Labor and materials to install Emergency Stop Button			
Diagnosis: Initial Work Order	Need to have a Light switch cover installed to keep the boilers from being turned off. POC is Mr. Mark Anderson (FC) at 804-371-5874 or Mr. Chris Chipps at 540-937-0768			
Diagnostic Fee	$160			
Additional Labor Cost to Perform Repairs	$480 TW Labor 6 hours @ $ 80/hr			
Additional Material Cost to Perform Repairs	$200.44			
	Emergency Push button	1	$200.44	$200.44
Total Cost of Repair	$840.44			

WORK ESTIMATE

CSS #:	22442	Work Order #:	11285
Emergency		Urgent	Routine: X

Company Name:	Tidewater, Inc.	Facility ID:	VA049
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	adam.colopy@tideh2o.net		
Assigned Technician(s):	Bill Davis/Richard Walker		

### DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Labor and materials to install Emergency Stop Button

ITEM	QUANTITY	MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR $80	LINE ITEM TOTAL DOLLAR AMOUNT
Labor			6	$480.00
Emergency Push button	1	$200.44		$200.44
Diagnostic Labor			2	$160.00
SUB-TOTAL COSTS:	Materials Total	$200.44	Labor	$640.00
		TOTAL		$840.44

🖶 Print   ✉ Email

SAFETY TECHNOLOGY INTERNATIONAL

Emergency Power Off Push Button, 3-1/4' Width, Polycarbonate

Item # **54JF37**   Mfr. Model # **SS2271PO-EN**   Catalog Page # **N/A**   UNSPSC # **46171503**

How can we improve our Product Images?

☐ Compare

Web Price ⓘ

$159.08 / each

| 1 | Add to Cart |

+ Add to List |

◉ Shipping   ○ Pickup

Expected to arrive **Fri. Dec 06**.

Ship To **43065** (Change)

Shipping Weight **1.66 lbs.**

Country of Origin **USA** | Country of Origin is subject to change.

Note: Product availability is real-time updated and adjusted continuously. The product will be reserved for you when you complete your order.
More

BoilER

EMERGENCY

Kill SwiTCH