Additional Funding Request

MD003	CSS# 22848 WO# 11463 Asset# NA
Description of Repairs	Labor and materials for getting rid of the door on Office 124 because it doesn't meet security standards. Then taking the door from 109 and install it on 124's frame. Then taking a door from storage and installing it on rm 109. Then install 3 cypher locks on rooms 109,124, & 207.
Diagnosis: Initial Work Order	There are three doors that require additional locks in order to meet physical security requirements. I have dropped off 3 cypher locks to be used on for this, they just need to be installed. The rooms are 109, 124 and 209. The doors will need to be drilled in order for the cypher locks to be installed. I also have the specialty keys and the template for the holes for the cypher locks and they cannot be installed without them, therefore, I will need to know when they are being installed.
Diagnostic Fee	$ 160 Labor $80/hr x 2
Additional Labor Cost to Perform Repairs	$ 640 Labor $80/hr x 8
Additional Cost	$ 171.36 | Latches including tax	2	$171.36	171.36	
Total Cost of Repair	$ 971.36

WORK ESTIMATE

CSS #:	22848	Work Order #:	11463
Emergency		Urgent	Routine **X**

Company Name:	Tidewater, Inc.	Facility ID:	MD003
Contractor POC:	Adam Colopy		
Telephone No:	740-819-6207	Building/Location; (e.g., Classroom/Room #)	
E-Mail Address:	adam.colopy@tideh2o.net		
Assigned Technician(s):	John Brown		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

The work to be done is getting rid of the door on Office 124 because it doesn't meet security standards. Then taking the door from 109 and install it on 124 frame. Then taking a door from storage and installing it on rm 109. Then install 3 cypher locks on rooms 109,124, & 207

LABOR/MATERIAL ITEM	QUANTITY	MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR $80	LINE ITEM TOTAL DOLLAR AMOUNT
Labor			8	$640.00
Latches	2	$81.60		$163.20
	TAX	$8.16		$8.16
Diagnostic			2	$160.00
SUB-TOTAL COSTS:	Materials Total	$171.36	Labor	$800.00
		TOTAL		$971.36

MS

MARYLAND SECURITY INC.
8 Aquahart Road • Suite 400
Glen Burnie, MD 21061
410-760-5625   Federal ID 75-3005813
sales@marylandsecurity.com

DATE **2.3.2020**

NAME **TIDE WATER**   PHONE **443 546 4349**

ADDRESS

APARTMENT   DATE PROMISED

SERIAL NO.   DATE OF ORIGINAL INSTALLATION

MAKE   MODEL

- [ ] ESTIMATE   - [ ] CASH
- [ ] WARRANTY   - [ ] CHARGE
- [ ] CONTRACT   - [ ] C.O.D.

NATURE OF SERVICE

QTY.	DESCRIPTION	PRICE	AMOUNT
1	2 3/8 KABA Dead Catch		68 00
	NET 30		
X	Johnny W. Brown		

COMMENTS

X **JWB**

TECHNICIAN

Signature below constitutes acceptance of above service performed as being satisfactory — and that the equipment has been left in good condition.

TOTAL MATERIALS		68.00
TECHNICAL SERVICE TIME - [ ] SHOP - [ ] HOME		
- [ ] PICK UP OR DELIVERY - [ ] SERVICE CALL CHARGE		
DATE COMPLETED	TAX	4.08
	TOTAL	72.05

№ 35955   **INVOICE**   *Thank You*

109

LISTED
6GA7
INT LOCK OF

TB

207

OFF LIMITS TO
UNAUTHORIZED
PERSONNEL