Additional Funding Request

VA050	CSS# 25417 WO# 12339 Asset# NA
Description of Repairs	LoCurrent Systems will perform a system update to accommodate recent deployed G&D CAC 7.0
Diagnosis: Initial Work Order	Flash CAC readers with new firmware. Current CAC readers do not recognize newly issued CAC/ID cards
Diagnostic Fee	$ 0.00
Additional Labor Cost to Perform Repairs	$ 950.00 Labor $75/hr x 12 and Admin Fee
Additional Cost	$ 0.00
Total Cost of Repair	$ 950.00

LoCurrent Systems, LLC
3522 County Highway 11
Cooperstown, NY 13326
(607)293-7300
locurrent@gmail.com

Estimate

ADDRESS	ESTIMATE #	1568
Tidewater Inc.	DATE	06/09/2020
6625- A Selnick Drive		
Elkridge, MD 21075		

P.O. NUMBER	SALES REP
Strathmore Richmond VA Rr Flash	A LoRusso

	ACTIVITY	QTY		AMOUNT
06/03/2020	**Installation Service** CSS#25417 WO#12339 Strathmore Center Richmond, VA USARC VA050 Access Control System Update Dear Mr. Colopy: As per your request, LoCurrent Systems is pleased to provide a quotation to perform System Update to accommodate recent deployed G&D CAC 7.0 at the Strathmore Center Richmond, VA USARC. Cost Breakdown: (2) men 6 hours ea. @ $75...$900.00 Administrative...$50.00 The cost for the above mentioned work is $950.00. If acceptable, please do not hesitate to contact us so that we may schedule for work to be completed. Thank you. Sincerely, Antonietta LoRusso	1	950.00	950.00

TOTAL	**$950.00**