Additional Funding Request

VA099	CSS# 25428 WO# 12340 Asset# NA
Description of Repairs	LoCurrent Systems will perform a system update to accommodate recent deployed G&D CAC 7.0
Diagnosis: Initial Work Order	Flash CAC readers with new firmware. Current CAC readers do not recognize newly issued CAC/ID cards
Diagnostic Fee	$ 0.00
Additional Labor Cost to Perform Repairs	$ 1,250.00 Labor $75/hr x 16 and Admin Fee
Additional Cost	$ 0.00
Total Cost of Repair	$ 1,250.00

LoCurrent Systems, LLC
3522 County Highway 11
Cooperstown, NY 13326
(607)293-7300
locurrent@gmail.com

Estimate

ADDRESS
Tidewater Inc.
6625- A Selnick Drive
Elkridge, MD 21075

ESTIMATE # 1564
DATE 06/09/2020

P.O. NUMBER
Bedford, VA Reader Flash

SALES REP
A. LoRusso

	ACTIVITY	QTY		AMOUNT
06/03/2020	**Installation Service** CSS# 25428 WO# 12340 Bedford, VA USARC VA099 Access Control System Update Dear Mr. Colopy: As per your request, LoCurrent Systems is pleased to provide a quotation to perform System Update to accommodate recent deployed G&D CAC 7.0 at the Bedford, VA USARC. Cost Breakdown: (2) men 8 hours @ $75...$1,200.00 Administrative...$50.00 The cost for the above mentioned work is $1,250.00. If acceptable, please do not hesitate to contact us so that we may schedule for work to be completed. Thank you. Sincerely, Antonietta LoRusso	1	1,250.00	1,250.00

Bedford, VA

TOTAL

$1,250.00