CERTIFICATION OF WORK
SERVICE CALL

(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: USARC VA099 Date of Visit: 01/05/2021

Contractor Personnel on Site:

1. HOWARD FLOYD
2. _____
3. _____
4. _____
5. _____
6. _____

Service Call Number

CSS# 27986 WO# COM01446085

Description of Repairs

HWB-1: REMOVED/REPLACED DEFECTIVE IGNITOR ASSEMBLY. STARTED UP & CK'D OPERATIONS & DIAGNOSTICS. SYSTEM IS NOW OPERATING PER MANUFACTURERS SPECIFICATIONS.

LEFT DEFECTIVE IGNITOR ON SITE FOR REVIEW IF NEEDED.

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: HOWARD FLOYD Date: 01/05/2021

Signed: Howard Floyd

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Shantel Roundtree, SFC Date: 5 JAN 2021

Signed: Shantel Roundtree

E-Mail: Shantel.L.Roundtree.mil@mail.mil

COMMERCIAL BOILER

XL

93.0

1

SYSTEM: 141°F(150)

OUTLET: 185°F(185)

MENU SRSCREEN SHDN

SMART SYSTEM

Select

Select

KNIGHT
COMMERCIAL BOILER
XL

88%

1

SYSTEM: 152°F(150)
OUTLET: 171°F(165)

MENU ↓SETPOINT SHDN

SMART SYSTEM

Select

Select

ASSET N°
2369